

In 1976 the 911 engine's oil bypass system was changed to make up for the different scavenge-to-pressure-pump ratio of the new-style oil pump. The bypassed oil is returned to the pressure pump inlet rather than being bypassed into the crankcase's sump.

5. Plug (new)

7. Vent passage

6. Return passage 11mm

8. Pressure oil passage